

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin

LD0001G	Total LMA Miles		12.45									
Levee District No. 0001G (Glenn County)	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.74		2.74	22.01	0.97		0.97	7.79	-1.77		-1.77	-14.22
Trim / Thin Trees	1.14		1.14	9.16	0.11		0.11	0.88	-1.03		-1.03	-8.27
Encroachments					0.37		0.37	2.97	0.37		0.37	2.97
Animal Control					0.74		0.74	5.94	0.74		0.74	5.94
Erosion / Bank Caving	0.01	0.19	0.77	6.18					-0.01	-0.19	-0.77	-6.18
<i>LMA Totals:</i>	3.89	0.19	4.65	37.35	2.19	0.00	2.19	17.59	-1.70	-0.19	-2.46	-19.76

LD0001S	Total LMA Miles		16.65									
Levee District No. 0001S (Sutter County)	Fall 2007				Fall 2008				Change			
	Overall LMA Rating M				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.84		0.84	5.05					-0.84		-0.84	-5.05
Encroachments	0.85		0.85	5.11					-0.85		-0.85	-5.11
Erosion / Bank Caving		0.23	0.92	5.53					0.00	-0.23	-0.92	-5.53
<i>LMA Totals:</i>	1.69	0.23	2.61	15.68	0.00	0.00	0.00	0.00	-1.69	-0.23	-2.61	-15.68

LD0002	Total LMA Miles		4.89									
Levee District No. 0002	Fall 2007				Fall 2008				Change			
	Overall LMA Rating A				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.17		0.17	3.48					-0.17		-0.17	-3.48
<i>LMA Totals:</i>	0.17	0.00	0.17	3.48	0.00	0.00	0.00	0.00	-0.17	0.00	-0.17	-3.48

LD0003	Total LMA Miles		12.24									
Levee District No. 0003	Fall 2007				Fall 2008				Change			
	Overall LMA Rating A				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.20		0.20	1.63					-0.20		-0.20	-1.63
Trim / Thin Trees	0.29		0.29	2.37					-0.29		-0.29	-2.37
Encroachments	0.05		0.05	0.41	0.01		0.01	0.08	-0.04		-0.04	-0.33
Animal Control					0.66		0.66	5.39	0.66		0.66	5.39
Slope Stability					0.03		0.03	0.25	0.03		0.03	0.25
Erosion / Bank Caving	0.02		0.02	0.16					-0.02		-0.02	-0.16
Crown Surface / Depressions / Rutting	0.02		0.02	0.16	0.04		0.04	0.33	0.02		0.02	0.16
<i>LMA Totals:</i>	0.58	0.00	0.58	4.74	0.74	0.00	0.74	6.05	0.16	0.00	0.16	1.31

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

LD0009	Total LMA Miles		6.24									
Levee District No. 0009	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control					0.01		0.01	0.16	0.01		0.01	0.16
Erosion / Bank Caving					0.07		0.07	1.12	0.07		0.07	1.12
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.08	0.00	0.08	1.28	0.08	0.00	0.08	1.28

MA0001	Total LMA Miles		17.10									
Maintenance Area 0001	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.33		0.33	1.93	0.01		0.01	0.06	-0.32		-0.32	-1.87
Trim / Thin Trees	1.21		1.21	7.08	0.05		0.05	0.29	-1.16		-1.16	-6.78
Encroachments	0.25		0.25	1.46	0.06		0.06	0.35	-0.19		-0.19	-1.11
Animal Control					1.90		1.90	11.11	1.90		1.90	11.11
Erosion / Bank Caving	0.04		0.04	0.23	0.01		0.01	0.06	-0.03		-0.03	-0.18
<i>LMA Totals:</i>	1.83	0.00	1.83	10.70	2.03	0.00	2.03	11.87	0.20	0.00	0.20	1.17

MA0003	Total LMA Miles		5.20									
Maintenance Area 0003	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments					0.12		0.12	2.31	0.12		0.12	2.31
Animal Control					0.01		0.01	0.19	0.01		0.01	0.19
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.13	0.00	0.13	2.50	0.13	0.00	0.13	2.50

MA0004	Total LMA Miles		3.40									
Maintenance Area 0004	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.18		0.18	5.29					-0.18		-0.18	-5.29
Animal Control	0.03		0.03	0.88	0.01		0.01	0.29	-0.02		-0.02	-0.59
<i>LMA Totals:</i>	0.21	0.00	0.21	6.18	0.01	0.00	0.01	0.29	-0.20	0.00	-0.20	-5.88

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

MA0005	Total LMA Miles		33.40									
Maintenance Area 0005	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	M				M *							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.21		0.21	0.63	0.10		0.10	0.30	-0.11		-0.11	-0.33
Trim / Thin Trees	0.61		0.61	1.83	0.20		0.20	0.60	-0.41		-0.41	-1.23
Encroachments	2.21		2.21	6.62	0.05		0.05	0.15	-2.16		-2.16	-6.47
Animal Control					0.37		0.37	1.11	0.37		0.37	1.11
Slope Stability					0.02		0.02	0.06	0.02		0.02	0.06
Crown Surface / Depressions / Rutting	1.50		1.50	4.49					-1.50		-1.50	-4.49
Repair Gates					0.01		0.01	0.03	0.01		0.01	0.03
Boat Survey Erosion						0.01	0.04	0.12	0.00	0.01	0.04	0.12
<i>LMA Totals:</i>	4.53	0.00	4.53	13.56	0.75	0.01	0.79	2.37*	-3.78	0.01	-3.74	-11.20
MA0007	Total LMA Miles		12.10									
Maintenance Area 0007	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.09		1.09	9.01					-1.09		-1.09	-9.01
Trim / Thin Trees	0.25		0.25	2.07					-0.25		-0.25	-2.07
Encroachments	0.92		0.92	7.60	0.02		0.02	0.17	-0.90		-0.90	-7.44
Animal Control	0.04		0.04	0.33	0.03		0.03	0.25	-0.01		-0.01	-0.08
Erosion / Bank Caving	0.10	0.18	0.82	6.78	0.07		0.07	0.58	-0.03	-0.18	-0.75	-6.20
<i>LMA Totals:</i>	2.40	0.18	3.12	25.79	0.12	0.00	0.12	0.99	-2.28	-0.18	-3.00	-24.79
MA0009	Total LMA Miles		19.60									
Maintenance Area 0009	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	M				M *							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.75		0.75	3.83	0.15		0.15	0.77	-0.60		-0.60	-3.06
Trim / Thin Trees	0.01		0.01	0.05	0.17		0.17	0.87	0.16		0.16	0.82
Encroachments	0.02		0.02	0.10	0.05		0.05	0.26	0.03		0.03	0.15
Animal Control					0.01		0.01	0.05	0.01		0.01	0.05
Slope Stability	0.01		0.01	0.05					-0.01		-0.01	-0.05
Erosion / Bank Caving	0.01	0.29	1.17	5.97					-0.01	-0.29	-1.17	-5.97
Boat Survey Erosion						0.04	0.16	0.82	0.00	0.04	0.16	0.82
<i>LMA Totals:</i>	0.80	0.29	1.96	10.00	0.38	0.04	0.54	2.76*	-0.42	-0.25	-1.42	-7.24
MA0012	Total LMA Miles		11.30									
Maintenance Area 0012	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	A				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control					0.02		0.02	0.18	0.02		0.02	0.18
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.02	0.00	0.02	0.18	0.02	0.00	0.02	0.18

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

MA0013	Total LMA Miles		42.00									
Maintenance Area 0013	Fall 2007				Fall 2008				Change			
	Overall LMA Rating A				Overall LMA Rating M *							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.07		0.07	0.17	0.07		0.07	0.17
Trim / Thin Trees	0.01		0.01	0.02	0.26		0.26	0.62	0.25		0.25	0.60
Encroachments	0.19		0.19	0.45	0.55		0.55	1.31	0.36		0.36	0.86
Animal Control					0.01		0.01	0.02	0.01		0.01	0.02
Erosion / Bank Caving	0.37		0.37	0.88	0.17	0.36	1.61	3.83	-0.20	0.36	1.24	2.95
Boat Survey Erosion					0.37		0.37	0.88	0.37		0.37	0.88
<i>LMA Totals:</i>	0.57	0.00	0.57	1.36	1.43	0.36	2.87	6.83*	0.86	0.36	2.30	5.48
MA0016	Total LMA Miles		4.10									
Maintenance Area 0016	Fall 2007				Fall 2008				Change			
	Overall LMA Rating M				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.33		0.33	8.05	0.33		0.33	8.05
Encroachments	0.31		0.31	7.56	0.02		0.02	0.49	-0.29		-0.29	-7.07
Animal Control	0.27		0.27	6.59	0.25		0.25	6.10	-0.02		-0.02	-0.49
<i>LMA Totals:</i>	0.58	0.00	0.58	14.15	0.60	0.00	0.60	14.63	0.02	0.00	0.02	0.49
NA0001	Total LMA Miles		34.12									
American River Flood Control District	Fall 2007				Fall 2008				Change			
	Overall LMA Rating M *				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.01		0.01	0.03					-0.01		-0.01	-0.03
Encroachments	1.49		1.49	4.37	0.02		0.02	0.06	-1.47		-1.47	-4.31
Erosion / Bank Caving	0.03	0.12	0.51	1.49					-0.03	-0.12	-0.51	-1.49
<i>LMA Totals:</i>	1.53	0.12	2.01	5.89*	0.02	0.00	0.02	0.06	-1.51	-0.12	-1.99	-5.83
NA0002	Total LMA Miles		19.30									
Brannan Andrus Levee Maintenance District	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	22.91	12.77	73.99	383.37	0.78	0.57	3.06	15.85	-22.13	-12.20	-70.93	-367.51
Trim / Thin Trees	4.38	1.12	8.86	45.91	0.61	0.44	2.37	12.28	-3.77	-0.68	-6.49	-33.63
Encroachments	0.01		0.01	0.05	0.02		0.02	0.10	0.01		0.01	0.05
Erosion / Bank Caving		0.21	0.84	4.35					0.00	-0.21	-0.84	-4.35
Boat Survey Erosion					0.01		0.04	0.21	0.00	0.01	0.04	0.21
<i>LMA Totals:</i>	27.30	14.10	83.70	433.68	1.41	1.02	5.49	28.45	-25.89	-13.08	-78.21	-405.23

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

NA0003		Total LMA Miles		24.74									
Butte County Public Works		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		0.01		0.01	0.04	0.01		0.01	0.04	0.00			0.00
Trim / Thin Trees		0.07		0.07	0.28					-0.07		-0.07	-0.28
Encroachments						0.41		0.41	1.66	0.41		0.41	1.66
Animal Control						0.05		0.05	0.20	0.05		0.05	0.20
Slope Stability						0.01		0.01	0.04	0.01		0.01	0.04
Erosion / Bank Caving		0.10		0.10	0.40					-0.10		-0.10	-0.40
Crown Surface / Depressions / Rutting		0.39		0.39	1.58					-0.39		-0.39	-1.58
LMA Totals:		0.57	0.00	0.57	2.30	0.48	0.00	0.48	1.94	-0.09	0.00	-0.09	-0.36

NA0004		Total LMA Miles		11.40									
Marysville Levee Commission		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		1.16		1.16	10.18					-1.16		-1.16	-10.18
LMA Totals:		1.16	0.00	1.16	10.18	0.00	0.00	0.00	0.00	-1.16	0.00	-1.16	-10.18

NA0005		Total LMA Miles		3.60									
City of Sacramento		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation						0.01		0.01	0.28	0.01		0.01	0.28
Trim / Thin Trees		1.66		1.66	46.11					-1.66		-1.66	-46.11
LMA Totals:		1.66	0.00	1.66	46.11	0.01	0.00	0.01	0.28	-1.65	0.00	-1.65	-45.83

NA0006		Total LMA Miles		1.50									
Eastern Honcut Creek		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		3.00		3.00	200.00	2.96		2.96	197.33	-0.04		-0.04	-2.67
Trim / Thin Trees		0.10		0.10	6.67					-0.10		-0.10	-6.67
Encroachments		0.31		0.31	20.67					-0.31		-0.31	-20.67
Crown Surface / Depressions / Rutting		0.05		0.05	3.33	0.73		0.73	48.67	0.68		0.68	45.33
LMA Totals:		3.46	0.00	3.46	230.67	3.69	0.00	3.69	246.00	0.23	0.00	0.23	15.33

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

NA0007	Total LMA Miles		3.01									
East Interceptor Canal	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.45		2.45	81.40	3.17		3.17	105.32	0.72		0.72	23.92
Trim / Thin Trees	0.15		0.15	4.98					-0.15		-0.15	-4.98
Encroachments	0.13		0.13	4.32	0.12		0.12	3.99	-0.01		-0.01	-0.33
Erosion / Bank Caving					0.39		0.39	12.96	0.39		0.39	12.96
Crown Surface / Depressions / Rutting	0.40		0.40	13.29					-0.40		-0.40	-13.29
<i>LMA Totals:</i>	3.13	0.00	3.13	103.99	3.68	0.00	3.68	122.26	0.55	0.00	0.55	18.27

NA0008	Total LMA Miles		12.60									
Knights Landing Ridge Drainage District	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.28		0.28	2.22	0.08		0.08	0.64	-0.20		-0.20	-1.59
Trim / Thin Trees	0.11		0.11	0.87	0.01		0.01	0.08	-0.10		-0.10	-0.79
Encroachments	0.54		0.54	4.29	0.01		0.01	0.08	-0.53		-0.53	-4.21
Animal Control					0.05		0.05	0.40	0.05		0.05	0.40
Erosion / Bank Caving	2.27		2.27	18.02					-2.27		-2.27	-18.02
Crown Surface / Depressions / Rutting	6.67		6.67	52.94					-6.67		-6.67	-52.94
Boat Survey Erosion					2.27		2.27	18.02	2.27		2.27	18.02
<i>LMA Totals:</i>	9.87	0.00	9.87	78.33	2.42	0.00	2.42	19.21	-7.45	0.00	-7.45	-59.13

NA0012	Total LMA Miles		0.59									
Solano County Public Works (Mellin Levee)	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.15		0.15	25.42	0.59		0.59	100.00	0.44		0.44	74.58
Encroachments	0.03		0.03	5.09	0.02		0.02	3.39	-0.01		-0.01	-1.70
Slope Stability	0.06		0.06	10.17	0.01		0.01	1.70	-0.05		-0.05	-8.47
Crown Surface / Depressions / Rutting	0.19		0.19	32.20	0.31		0.31	52.54	0.12		0.12	20.34
<i>LMA Totals:</i>	0.43	0.00	0.43	72.88	0.93	0.00	0.93	157.63	0.50	0.00	0.50	84.75

NA0014	Total LMA Miles		0.78									
Murphy Slough at M&T Ranch	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.31	0.82	3.59	460.26	1.30		1.30	166.67	0.99	-0.82	-2.29	-293.59
Trim / Thin Trees					0.62		0.62	79.49	0.62		0.62	79.49
<i>LMA Totals:</i>	0.31	0.82	3.59	460.26	1.92	0.00	1.92	246.15	1.61	-0.82	-1.67	-214.10

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

NA0016	Total LMA Miles		50.24									
Sacramento River West Side Levee District	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M *							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.99		3.99	7.94	0.05		0.05	0.10	-3.94		-3.94	-7.84
Trim / Thin Trees	3.68		3.68	7.33	0.04		0.04	0.08	-3.64		-3.64	-7.25
Encroachments	1.00		1.00	1.99	0.05		0.05	0.10	-0.95		-0.95	-1.89
Animal Control	100.48		100.48	200.00	0.15		0.15	0.30	-100.33		-100.33	-199.70
Erosion / Bank Caving	0.05		0.05	0.10					-0.05		-0.05	-0.10
Boat Survey Erosion					0.04		0.16	0.32	0.00	0.04	0.16	0.32
<i>LMA Totals:</i>	109.20	0.00	109.20	217.36	0.29	0.04	0.45	0.90*	-108.91	0.04	-108.75	-216.46

NA0018	Total LMA Miles		0.30									
California Department of Fish and Game	Fall 2007				Fall 2008				Change			
	Overall LMA Rating A				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
No Items									0.00		0.00	0.00
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

NA0019	Total LMA Miles		13.64									
Tehama County Flood Control and Water Conservation District	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.46		1.46	10.70	0.66		0.66	4.84	-0.80		-0.80	-5.87
Trim / Thin Trees	3.48		3.48	25.51	0.14		0.14	1.03	-3.34		-3.34	-24.49
Encroachments	0.90		0.90	6.60	0.65		0.65	4.77	-0.25		-0.25	-1.83
Animal Control					0.01		0.01	0.07	0.01		0.01	0.07
Slope Stability					0.25		0.25	1.83	0.25		0.25	1.83
Erosion / Bank Caving	0.20	0.05	0.40	2.93	0.01		0.01	0.07	-0.19	-0.05	-0.39	-2.86
Crown Surface / Depressions / Rutting	0.25		0.25	1.83					-0.25		-0.25	-1.83
Boat Survey Erosion					0.07		0.07	0.51	0.07		0.07	0.51
<i>LMA Totals:</i>	6.29	0.05	6.49	47.58	1.79	0.00	1.79	13.12	-4.50	-0.05	-4.70	-34.46

NA0020	Total LMA Miles		1.75									
West Interceptor Canal	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.52		0.52	29.71	0.24		0.24	13.71	-0.28		-0.28	-16.00
Encroachments	0.04		0.04	2.29	0.04		0.04	2.29	0.00			0.00
Erosion / Bank Caving	0.02		0.02	1.14	0.04		0.04	2.29	0.02		0.02	1.14
<i>LMA Totals:</i>	0.58	0.00	0.58	33.14	0.32	0.00	0.32	18.29	-0.26	0.00	-0.26	-14.86

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

NA0021	Total LMA Miles		0.29									
Yolo County Public Works	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.66		0.66	227.59					-0.66		-0.66	-227.59
Trim / Thin Trees	0.23		0.23	79.31	0.05		0.05	17.24	-0.18		-0.18	-62.07
Encroachments	0.03		0.03	10.35					-0.03		-0.03	-10.35
Animal Control	0.29		0.29	100.00					-0.29		-0.29	-100.00
<i>LMA Totals:</i>	1.21	0.00	1.21	417.24	0.05	0.00	0.05	17.24	-1.16	0.00	-1.16	-400.00

NA0022	Total LMA Miles		5.97									
Yolo County Service Area 6	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	5.02		5.02	84.09	0.56		0.56	9.38	-4.46		-4.46	-74.71
Trim / Thin Trees	1.05		1.05	17.59	0.01		0.01	0.17	-1.04		-1.04	-17.42
Encroachments	4.19		4.19	70.18	0.05		0.05	0.84	-4.14		-4.14	-69.35
Erosion / Bank Caving	0.04		0.04	0.67					-0.04		-0.04	-0.67
<i>LMA Totals:</i>	10.30	0.00	10.30	172.53	0.62	0.00	0.62	10.39	-9.68	0.00	-9.68	-162.14

RD0003	Total LMA Miles		28.60									
Reclamation District No. 0003	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	24.97	0.01	25.01	87.45	35.38		35.38	123.71	10.41	-0.01	10.37	36.26
Trim / Thin Trees	3.89		3.89	13.60	3.94	0.64	6.50	22.73	0.05	0.64	2.61	9.13
Encroachments	0.01		0.01	0.04	0.17		0.17	0.59	0.16		0.16	0.56
Slope Stability					0.06		0.06	0.21	0.06		0.06	0.21
Erosion / Bank Caving	0.29		0.29	1.01					-0.29		-0.29	-1.01
Repair Gates					0.01		0.01	0.04	0.01		0.01	0.04
Boat Survey Erosion					0.29		0.29	1.01	0.29		0.29	1.01
<i>LMA Totals:</i>	29.16	0.01	29.20	102.10	39.85	0.64	42.41	148.29	10.69	0.63	13.21	46.19

RD0010	Total LMA Miles		21.90									
Reclamation District No. 0010	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.50		0.50	2.28	24.02		24.02	109.68	23.52		23.52	107.40
Trim / Thin Trees					0.05		0.05	0.23	0.05		0.05	0.23
Encroachments	0.25		0.25	1.14	0.02	0.12	0.50	2.28	-0.23	0.12	0.25	1.14
Animal Control	9.11		9.11	41.60	0.03		0.03	0.14	-9.08		-9.08	-41.46
Crown Surface / Depressions / Rutting	7.68		7.68	35.07					-7.68		-7.68	-35.07
Culverts: Inlets / Outlets					0.01		0.01	0.05	0.01		0.01	0.05
<i>LMA Totals:</i>	17.54	0.00	17.54	80.09	24.13	0.12	24.61	112.37	6.59	0.12	7.07	32.28

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD0070	Total LMA Miles		23.60									
Reclamation District No. 0070	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	M *				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.10		0.10	0.42					-0.10		-0.10	-0.42
Animal Control					0.07		0.07	0.30	0.07		0.07	0.30
Erosion / Bank Caving	0.01	0.36	1.45	6.14					-0.01	-0.36	-1.45	-6.14
Boat Survey Erosion					0.29		0.29	1.23	0.29		0.29	1.23
<i>LMA Totals:</i>	0.11	0.36	1.55	6.57*	0.36	0.00	0.36	1.53	0.25	-0.36	-1.19	-5.04
RD0108	Total LMA Miles		20.60									
Reclamation District No. 0108	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	A				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.02		0.02	0.10	0.02		0.02	0.10	0.00			0.00
Animal Control	0.11		0.11	0.53	0.02		0.02	0.10	-0.09		-0.09	-0.44
Crown Surface / Depressions / Rutting	0.73		0.73	3.54					-0.73		-0.73	-3.54
<i>LMA Totals:</i>	0.86	0.00	0.86	4.18	0.04	0.00	0.04	0.19	-0.82	0.00	-0.82	-3.98
RD0150	Total LMA Miles		18.07									
Reclamation District No. 0150	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				M *							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	10.72	1.40	16.32	90.32	0.22		0.22	1.22	-10.50	-1.40	-16.10	-89.10
Trim / Thin Trees	16.84		16.84	93.19	0.53		0.53	2.93	-16.31		-16.31	-90.26
Encroachments	0.21		0.21	1.16	0.13		0.13	0.72	-0.08		-0.08	-0.44
Animal Control					0.20		0.20	1.11	0.20		0.20	1.11
Slope Stability					0.03		0.03	0.17	0.03		0.03	0.17
Erosion / Bank Caving	0.08	0.09	0.44	2.43	0.08		0.08	0.44	0.00	-0.09	-0.36	-1.99
Crown Surface / Depressions / Rutting					0.01		0.01	0.06	0.01		0.01	0.06
Metal Pipes	0.01		0.01	0.06					-0.01		-0.01	-0.06
Boat Survey Erosion					0.03	0.09	0.39	2.16	0.03	0.09	0.39	2.16
<i>LMA Totals:</i>	27.86	1.49	33.82	187.16	1.23	0.09	1.59	8.80*	-26.63	-1.40	-32.23	-178.36
RD0307	Total LMA Miles		6.70									
Reclamation District No. 0307	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	7.66	6.65	34.26	511.34	1.33	1.94	9.09	135.67	-6.33	-4.71	-25.17	-375.67
Trim / Thin Trees	1.91	4.20	18.71	279.25	3.98	1.10	8.38	125.07	2.07	-3.10	-10.33	-154.18
Encroachments	0.02		0.02	0.30	0.07	0.03	0.19	2.84	0.05	0.03	0.17	2.54
Animal Control	13.30		13.30	198.51	0.06		0.06	0.90	-13.24		-13.24	-197.61
Boat Survey Erosion					0.01	0.04	0.04	0.60	0.00	0.01	0.04	0.60
<i>LMA Totals:</i>	22.89	10.85	66.29	989.40	5.44	3.08	17.76	265.07	-17.45	-7.77	-48.53	-724.33

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD0341	Total LMA Miles		9.70									
Reclamation District No. 0341	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.86	2.44	13.62	140.41	1.96	3.06	14.20	146.39	-1.90	0.62	0.58	5.98
Trim / Thin Trees	6.09		6.09	62.78					-6.09		-6.09	-62.78
Encroachments	1.46		1.46	15.05	0.15		0.15	1.55	-1.31		-1.31	-13.51
Slope Stability	0.12		0.12	1.24					-0.12		-0.12	-1.24
Erosion / Bank Caving		0.15	0.60	6.19					0.00	-0.15	-0.60	-6.19
Crown Surface / Depressions / Rutting	0.53		0.53	5.46					-0.53		-0.53	-5.46
LMA Totals:	12.06	2.59	22.42	231.13	2.11	3.06	14.35	147.94	-9.95	0.47	-8.07	-83.20

RD0349	Total LMA Miles		12.60									
Reclamation District No. 0349	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	14.58		14.58	115.71	9.39	0.20	10.19	80.87	-5.19	0.20	-4.39	-34.84
Trim / Thin Trees	9.10		9.10	72.22	0.54		0.54	4.29	-8.56		-8.56	-67.94
Encroachments	3.14		3.14	24.92	0.22	0.04	0.38	3.02	-2.92	0.04	-2.76	-21.91
Erosion / Bank Caving	0.04	0.26	1.08	8.57					-0.04	-0.26	-1.08	-8.57
Crown Surface / Depressions / Rutting	5.44		5.44	43.18					-5.44		-5.44	-43.18
Boat Survey Erosion					0.03	0.11	0.47	3.73	0.03	0.11	0.47	3.73
LMA Totals:	32.30	0.26	33.34	264.60	10.18	0.35	11.58	91.90	-22.12	0.09	-21.76	-172.70

RD0369	Total LMA Miles		0.80									
Reclamation District No. 0369	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.18		1.18	147.50	0.16	0.22	1.04	130.00	-1.02	0.22	-0.14	-17.50
Trim / Thin Trees	1.06		1.06	132.50	0.21	0.08	0.53	66.25	-0.85	0.08	-0.53	-66.25
LMA Totals:	2.24	0.00	2.24	280.00	0.37	0.30	1.57	196.25	-1.87	0.30	-0.67	-83.75

RD0501	Total LMA Miles		20.50									
Reclamation District No. 0501	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	48.20		48.20	235.12	16.03	2.00	24.03	117.22	-32.17	2.00	-24.17	-117.90
Trim / Thin Trees	2.63		2.63	12.83	0.78	1.13	5.30	25.85	-1.85	1.13	2.67	13.02
Encroachments	2.80		2.80	13.66	0.01	0.03	0.13	0.63	-2.79	0.03	-2.67	-13.02
Animal Control					3.30		3.30	16.10	3.30		3.30	16.10
Slope Stability		0.51	2.04	9.95					0.00	-0.51	-2.04	-9.95
Erosion / Bank Caving	0.08	0.04	0.24	1.17	0.06		0.06	0.29	-0.02	-0.04	-0.18	-0.88
Cracking					0.29	0.33	1.61	7.85	0.29	0.33	1.61	7.85
Crown Surface / Depressions / Rutting					0.18		0.18	0.88	0.18		0.18	0.88
Boat Survey Erosion					0.11	0.01	0.15	0.73	0.11	0.01	0.15	0.73
LMA Totals:	53.71	0.55	55.91	272.73	20.76	3.50	34.76	169.56	-32.95	2.95	-21.15	-103.17

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD0536	Total LMA Miles		10.70									
Reclamation District No. 0536	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.55	0.17	2.23	20.84	11.54	4.41	29.18	272.71	9.99	4.24	26.95	251.87
Trim / Thin Trees	0.08		0.08	0.75	0.08		0.08	0.75	0.00			0.00
Encroachments	3.63		3.63	33.93					-3.63		-3.63	-33.93
Animal Control	0.11		0.11	1.03					-0.11		-0.11	-1.03
Erosion / Bank Caving					0.01		0.01	0.09	0.01		0.01	0.09
Cracking	6.63		6.63	61.96					-6.63		-6.63	-61.96
Crown Surface / Depressions / Rutting	5.72	1.30	10.92	102.06	4.78	0.67	7.46	69.72	-0.94	-0.63	-3.46	-32.34
Repair Gates		0.02	0.08	0.75					0.00	-0.02	-0.08	-0.75
LMA Totals:	17.72	1.49	23.68	221.31	16.41	5.08	36.73	343.27	-1.31	3.59	13.05	121.96
RD0537	Total LMA Miles		6.00									
Reclamation District No. 0537	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	5.03		5.03	83.83	0.37		0.37	6.17	-4.66		-4.66	-77.67
Trim / Thin Trees	0.25		0.25	4.17					-0.25		-0.25	-4.17
Encroachments	2.02		2.02	33.67					-2.02		-2.02	-33.67
Erosion / Bank Caving	0.05		0.05	0.83					-0.05		-0.05	-0.83
Boat Survey Erosion					0.01		0.01	0.17	0.01		0.01	0.17
LMA Totals:	7.35	0.00	7.35	122.50	0.38	0.00	0.38	6.33	-6.97	0.00	-6.97	-116.17
RD0551	Total LMA Miles		6.80									
Reclamation District No. 0551	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.61	0.62	4.09	60.15	0.99	0.14	1.55	22.79	-0.62	-0.48	-2.54	-37.35
Trim / Thin Trees	2.41		2.41	35.44	0.07		0.07	1.03	-2.34		-2.34	-34.41
Encroachments	0.01		0.01	0.15	0.25	0.03	0.37	5.44	0.24	0.03	0.36	5.29
Animal Control					1.17		1.17	17.21	1.17		1.17	17.21
Crown Surface / Depressions / Rutting	0.01		0.01	0.15					-0.01		-0.01	-0.15
LMA Totals:	4.04	0.62	6.52	95.88	2.48	0.17	3.16	46.47	-1.56	-0.45	-3.36	-49.41
RD0554	Total LMA Miles		1.20									
Reclamation District No. 0554	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.07		1.07	89.17	0.01	0.83	3.33	277.50	-1.06	0.83	2.26	188.33
Trim / Thin Trees	0.75		0.75	62.50	0.04	0.14	0.60	50.00	-0.71	0.14	-0.15	-12.50
Encroachments					0.02	0.08	0.67	6.67	0.00	0.02	0.08	6.67
LMA Totals:	1.82	0.00	1.82	151.67	0.05	0.99	4.01	334.17	-1.77	0.99	2.19	182.50

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD0556	Total LMA Miles		11.20									
Reclamation District No. 0556	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	8.91	0.44	10.67	95.27	7.40	5.76	30.44	271.79	-1.51	5.32	19.77	176.52
Trim / Thin Trees	2.61		2.61	23.30	0.48	0.89	4.04	36.07	-2.13	0.89	1.43	12.77
Encroachments	0.40		0.40	3.57	0.05	0.03	0.17	1.52	-0.35	0.03	-0.23	-2.05
Slope Stability						0.29	1.16	10.36	0.00	0.29	1.16	10.36
Erosion / Bank Caving	0.36	0.48	2.28	20.36					-0.36	-0.48	-2.28	-20.36
Boat Survey Erosion					0.37	0.20	1.17	10.45	0.37	0.20	1.17	10.45
<i>LMA Totals:</i>	12.28	0.92	15.96	142.50	8.30	7.17	36.98	330.18	-3.98	6.25	21.02	187.68
RD0563	Total LMA Miles		12.40									
Reclamation District No. 0563	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	18.43	13.81	73.67	594.11	18.99	0.60	21.39	172.50	0.56	-13.21	-52.28	-421.61
Trim / Thin Trees	1.72	0.62	4.20	33.87	0.60	0.32	1.88	15.16	-1.12	-0.30	-2.32	-18.71
Encroachments	0.28		0.28	2.26	1.98	0.02	2.06	16.61	1.70	0.02	1.78	14.35
Slope Stability						0.01	0.04	0.32	0.00	0.01	0.04	0.32
Erosion / Bank Caving	2.08	0.51	4.12	33.23					-2.08	-0.51	-4.12	-33.23
Boat Survey Erosion					2.10	0.51	4.14	33.39	2.10	0.51	4.14	33.39
<i>LMA Totals:</i>	22.51	14.94	82.27	663.47	23.67	1.46	29.51	237.98	1.16	-13.48	-52.76	-425.48
RD0755	Total LMA Miles		1.90									
Reclamation District No. 0755	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.29		1.29	67.90	0.36		0.36	18.95	-0.93		-0.93	-48.95
Trim / Thin Trees	0.33		0.33	17.37	0.01		0.01	0.53	-0.32		-0.32	-16.84
Encroachments	0.19		0.19	10.00	0.01	0.01	0.05	2.63	-0.18	0.01	-0.14	-7.37
Animal Control	0.12		0.12	6.32	0.06		0.06	3.16	-0.06		-0.06	-3.16
Slope Stability					0.04		0.04	2.11	0.04		0.04	2.11
Erosion / Bank Caving		0.09	0.36	18.95					0.00	-0.09	-0.36	-18.95
Crown Surface / Depressions / Rutting					0.01		0.01	0.53	0.01		0.01	0.53
<i>LMA Totals:</i>	1.93	0.09	2.29	120.53	0.49	0.01	0.53	27.89	-1.44	-0.08	-1.76	-92.63
RD0765	Total LMA Miles		1.70									
Reclamation District No. 0765	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		0.36	1.44	84.71	0.07	0.24	1.03	60.59	0.07	-0.12	-0.41	-24.12
Trim / Thin Trees	0.83	0.17	1.51	88.82	0.53	0.14	1.09	64.12	-0.30	-0.03	-0.42	-24.71
Encroachments					0.01		0.01	0.59	0.01		0.01	0.59
<i>LMA Totals:</i>	0.83	0.53	2.95	173.53	0.61	0.38	2.13	125.29	-0.22	-0.15	-0.82	-48.24

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD0784	Total LMA Miles		35.20									
Reclamation District No. 0784	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.01		1.01	2.87	0.71		0.71	2.02	-0.30		-0.30	-0.85
Encroachments	2.10		2.10	5.97					-2.10		-2.10	-5.97
Erosion / Bank Caving	0.01	0.49	1.97	5.60	0.03		0.03	0.09	0.02	-0.49	-1.94	-5.51
Crown Surface / Depressions / Rutting	0.32		0.32	0.91					-0.32		-0.32	-0.91
<i>LMA Totals:</i>	3.44	0.49	5.40	15.34	0.74	0.00	0.74	2.10	-2.70	-0.49	-4.66	-13.24
RD0785	Total LMA Miles		5.60									
Reclamation District No. 0785	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.26		2.26	40.36	0.15		0.15	2.68	-2.11		-2.11	-37.68
Trim / Thin Trees	0.45		0.45	8.04					-0.45		-0.45	-8.04
Encroachments	0.16		0.16	2.86					-0.16		-0.16	-2.86
Erosion / Bank Caving	0.27		0.27	4.82					-0.27		-0.27	-4.82
<i>LMA Totals:</i>	3.14	0.00	3.14	56.07	0.15	0.00	0.15	2.68	-2.99	0.00	-2.99	-53.39
RD0787	Total LMA Miles		4.40									
Reclamation District No. 0787	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.10		0.10	2.27					-0.10		-0.10	-2.27
Encroachments	0.06		0.06	1.36					-0.06		-0.06	-1.36
Animal Control					0.04		0.04	0.91	0.04		0.04	0.91
<i>LMA Totals:</i>	0.16	0.00	0.16	3.64	0.04	0.00	0.04	0.91	-0.12	0.00	-0.12	-2.73
RD0817	Total LMA Miles		9.20									
Reclamation District No. 0817	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.99		0.99	10.76	0.11		0.11	1.20	-0.88		-0.88	-9.57
Trim / Thin Trees	0.33		0.33	3.59					-0.33		-0.33	-3.59
Encroachments	0.56		0.56	6.09	0.01		0.01	0.11	-0.55		-0.55	-5.98
Slope Stability	0.85		0.85	9.24					-0.85		-0.85	-9.24
Crown Surface / Depressions / Rutting	1.93		1.93	20.98	0.23		0.23	2.50	-1.70		-1.70	-18.48
Metal Pipes		0.01	0.04	0.43					0.00	-0.01	-0.04	-0.43
<i>LMA Totals:</i>	4.66	0.01	4.70	51.09	0.35	0.00	0.35	3.80	-4.31	-0.01	-4.35	-47.28

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD0827												
Reclamation District No. 0827												
Total LMA Miles		4.20										
Fall 2007				Fall 2008				Change				
Overall LMA Rating				Overall LMA Rating								
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.98		0.98	23.33	0.47		0.47	11.19	-0.51		-0.51	-12.14
Trim / Thin Trees	0.45		0.45	10.71	0.13		0.13	3.10	-0.32		-0.32	-7.62
Encroachments	1.46		1.46	34.76					-1.46		-1.46	-34.76
Animal Control					0.02		0.02	0.48	0.02		0.02	0.48
Crown Surface / Depressions / Rutting	2.49		2.49	59.29					-2.49		-2.49	-59.29
LMA Totals:	5.38	0.00	5.38	128.10	0.62	0.00	0.62	14.76	-4.76	0.00	-4.76	-113.33

RD0900												
Reclamation District No. 0900												
Total LMA Miles		13.60										
Fall 2007				Fall 2008				Change				
Overall LMA Rating				Overall LMA Rating								
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.39		2.39	17.57	4.09	0.64	6.65	48.90	1.70	0.64	4.26	31.32
Trim / Thin Trees	0.06		0.06	0.44	1.27	0.12	1.75	12.87	1.21	0.12	1.69	12.43
Encroachments	2.08		2.08	15.29	0.02		0.02	0.15	-2.06		-2.06	-15.15
Animal Control					0.29		0.29	2.13	0.29		0.29	2.13
Erosion / Bank Caving	0.04	0.09	0.40	2.94					-0.04	-0.09	-0.40	-2.94
Cracking					0.02		0.02	0.15	0.02		0.02	0.15
Crown Surface / Depressions / Rutting	0.94		0.94	6.91	1.64	0.18	2.36	17.35	0.70	0.18	1.42	10.44
Boat Survey Erosion						0.01	0.04	0.29	0.00	0.01	0.04	0.29
LMA Totals:	5.51	0.09	5.87	43.16	7.33	0.95	11.13	81.84	1.82	0.86	5.26	38.68

RD0999												
Reclamation District No. 0999												
Total LMA Miles		32.40										
Fall 2007				Fall 2008				Change				
Overall LMA Rating				Overall LMA Rating								
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		14.06	56.24	173.58	1.92	0.35	3.32	10.25	1.92	-13.71	-52.92	-163.33
Trim / Thin Trees	12.22	3.00	24.22	74.75	4.06	1.28	9.18	28.33	-8.16	-1.72	-15.04	-46.42
Encroachments	0.31		0.31	0.96	0.91		0.91	2.81	0.60		0.60	1.85
Animal Control					1.91		1.91	5.90	1.91		1.91	5.90
Erosion / Bank Caving	0.35	0.27	1.43	4.41					-0.35	-0.27	-1.43	-4.41
Crown Surface / Depressions / Rutting	0.40		0.40	1.24	0.29		0.29	0.90	-0.11		-0.11	-0.34
Boat Survey Erosion					0.02	0.34	1.38	4.26	0.02	0.34	1.38	4.26
LMA Totals:	13.28	17.33	82.60	254.94	9.11	1.97	16.99	52.44	-4.17	-15.36	-65.61	-202.50

RD1000												
Reclamation District No. 1000												
Total LMA Miles		42.60										
Fall 2007				Fall 2008				Change				
Overall LMA Rating				Overall LMA Rating								
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					1.30		1.30	3.05	1.30		1.30	3.05
Encroachments	2.14		2.14	5.02					-2.14		-2.14	-5.02
Erosion / Bank Caving	0.13		0.13	0.31					-0.13		-0.13	-0.31
Boat Survey Erosion					0.13		0.13	0.31	0.13		0.13	0.31
LMA Totals:	2.27	0.00	2.27	5.33	1.43	0.00	1.43	3.36	-0.84	0.00	-0.84	-1.97

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD1001	Total LMA Miles		44.00									
Reclamation District No. 1001	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	16.77	0.96	20.61	46.84	5.45		5.45	12.39	-11.32	-0.96	-15.16	-34.45
Trim / Thin Trees	2.19		2.19	4.98	0.11		0.11	0.25	-2.08		-2.08	-4.73
Encroachments	8.18		8.18	18.59	0.57		0.57	1.30	-7.61		-7.61	-17.30
Animal Control					0.02		0.02	0.05	0.02		0.02	0.05
Slope Stability					0.03		0.03	0.07	0.03		0.03	0.07
Erosion / Bank Caving	0.54	0.32	1.82	4.14					-0.54	-0.32	-1.82	-4.14
Crown Surface / Depressions / Rutting	4.56		4.56	10.36					-4.56		-4.56	-10.36
Sluice / Slide Gates					0.01		0.01	0.02	0.01		0.01	0.02
Boat Survey Erosion					0.03	0.04	0.19	0.43	0.03	0.04	0.19	0.43
LMA Totals:	32.24	1.28	37.36	84.91	6.22	0.04	6.38	14.50	-26.02	-1.24	-30.98	-70.41

RD1500	Total LMA Miles		54.40									
Reclamation District No. 1500	Fall 2007				Fall 2008				Change			
	Overall LMA Rating M				Overall LMA Rating M *							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.60		0.60	1.10					-0.60		-0.60	-1.10
Trim / Thin Trees	0.57		0.57	1.05					-0.57		-0.57	-1.05
Encroachments	2.91		2.91	5.35	0.03		0.03	0.06	-2.88		-2.88	-5.29
Animal Control					0.07		0.07	0.13	0.07		0.07	0.13
Erosion / Bank Caving	0.50	0.68	3.22	5.92	0.05		0.05	0.09	-0.45	-0.68	-3.17	-5.83
Boat Survey Erosion					0.49	0.47	2.37	4.36	0.49	0.47	2.37	4.36
LMA Totals:	4.58	0.68	7.30	13.42	0.64	0.47	2.52	4.63*	-3.94	-0.21	-4.78	-8.79

RD1600	Total LMA Miles		14.70									
Reclamation District No. 1600	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.62		3.62	24.63	0.99		0.99	6.74	-2.63		-2.63	-17.89
Trim / Thin Trees	2.88		2.88	19.59	0.01		0.01	0.07	-2.87		-2.87	-19.52
Encroachments	0.11		0.11	0.75	0.08		0.08	0.54	-0.03		-0.03	-0.20
Animal Control	3.77		3.77	25.65					-3.77		-3.77	-25.65
Erosion / Bank Caving	0.03		0.03	0.20	0.66		0.66	4.49	0.63		0.63	4.29
Crown Surface / Depressions / Rutting	0.12		0.12	0.82					-0.12		-0.12	-0.82
Metal Pipes	0.01		0.01	0.07					-0.01		-0.01	-0.07
LMA Totals:	10.54	0.00	10.54	71.70	1.74	0.00	1.74	11.84	-8.80	0.00	-8.80	-59.86

RD1601	Total LMA Miles		2.50									
Reclamation District No. 1601	Fall 2007				Fall 2008				Change			
	Overall LMA Rating A				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments	0.02		0.02	0.80					-0.02		-0.02	-0.80
LMA Totals:	0.02	0.00	0.02	0.80	0.00	0.00	0.00	0.00	-0.02	0.00	-0.02	-0.80

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD1660	Total LMA Miles		12.10									
Reclamation District No. 1660	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	A				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.02		0.02	0.17					-0.02		-0.02	-0.17
Encroachments	0.01		0.01	0.08	0.01		0.01	0.08	0.00			0.00
Animal Control	0.01		0.01	0.08	0.04		0.04	0.33	0.03		0.03	0.25
Erosion / Bank Caving	0.04		0.04	0.33					-0.04		-0.04	-0.33
<i>LMA Totals:</i>	0.08	0.00	0.08	0.66	0.05	0.00	0.05	0.41	-0.03	0.00	-0.03	-0.25
RD2035	Total LMA Miles		12.10									
Reclamation District No. 2035	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	3.96		3.96	32.73					-3.96		-3.96	-32.73
Erosion / Bank Caving	0.73		0.73	6.03					-0.73		-0.73	-6.03
Boat Survey Erosion					0.73		0.73	6.03	0.73		0.73	6.03
<i>LMA Totals:</i>	4.69	0.00	4.69	38.76	0.73	0.00	0.73	6.03	-3.96	0.00	-3.96	-32.73
RD2060	Total LMA Miles		16.00									
Reclamation District No. 2060	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	U				M							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.02		1.02	6.38	2.71		2.71	16.94	1.69		1.69	10.56
Trim / Thin Trees					0.03		0.03	0.19	0.03		0.03	0.19
Encroachments	0.02		0.02	0.13					-0.02		-0.02	-0.13
Erosion / Bank Caving	0.31		0.31	1.94	0.01		0.01	0.06	-0.30		-0.30	-1.88
Crown Surface / Depressions / Rutting	2.37		2.37	14.81					-2.37		-2.37	-14.81
Repair Gates						0.02	0.08	0.50	0.00	0.02	0.08	0.50
<i>LMA Totals:</i>	3.72	0.00	3.72	23.25	2.75	0.02	2.83	17.69	-0.97	0.02	-0.89	-5.56
RD2068	Total LMA Miles		8.73									
Reclamation District No. 2068	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
	A				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.06		0.06	0.69	0.06		0.06	0.69
Animal Control	0.77		0.77	8.82					-0.77		-0.77	-8.82
<i>LMA Totals:</i>	0.77	0.00	0.77	8.82	0.06	0.00	0.06	0.69	-0.71	0.00	-0.71	-8.13

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

RD2098	Total LMA Miles		11.02									
Reclamation District No. 2098	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.52		0.52	4.72	0.66		0.66	5.99	0.14		0.14	1.27
Trim / Thin Trees	0.10		0.10	0.91					-0.10		-0.10	-0.91
Encroachments	0.01		0.01	0.09					-0.01		-0.01	-0.09
Erosion / Bank Caving	0.88		0.88	7.99	0.06		0.06	0.54	-0.82		-0.82	-7.44
<i>LMA Totals:</i>	1.51	0.00	1.51	13.70	0.72	0.00	0.72	6.53	-0.79	0.00	-0.79	-7.17
RD2103	Total LMA Miles		9.80									
Reclamation District No. 2103	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.38		0.38	3.88					-0.38		-0.38	-3.88
Encroachments	0.12		0.12	1.22		0.01	0.04	0.41	-0.12	0.01	-0.08	-0.82
Animal Control					0.02		0.02	0.20	0.02		0.02	0.20
Crown Surface / Depressions / Rutting					0.74		0.74	7.55	0.74		0.74	7.55
Repair Gates						0.01	0.04	0.41	0.00	0.01	0.04	0.41
<i>LMA Totals:</i>	0.50	0.00	0.50	5.10	0.76	0.02	0.84	8.57*	0.26	0.02	0.34	3.47
RD2104	Total LMA Miles		7.40									
Reclamation District No. 2104	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.42	0.10	0.82	11.08	1.78	7.01	29.82	402.97	1.36	6.91	29.00	391.89
Trim / Thin Trees					0.02	0.05	0.22	2.97	0.02	0.05	0.22	2.97
Encroachments	0.03		0.03	0.41					-0.03		-0.03	-0.41
Erosion / Bank Caving					0.01		0.01	0.14	0.01		0.01	0.14
Crown Surface / Depressions / Rutting	4.11		4.11	55.54					-4.11		-4.11	-55.54
Repair Gates						0.01	0.04	0.54	0.00	0.01	0.04	0.54
<i>LMA Totals:</i>	4.56	0.10	4.96	67.03	1.81	7.07	30.09	406.62	-2.75	6.97	25.13	339.59
ST0001	Total LMA Miles		25.83									
Cache Creek	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.02		0.02	0.08	0.02		0.02	0.08
Trim / Thin Trees	0.21		0.21	0.81					-0.21		-0.21	-0.81
Encroachments	0.68		0.68	2.63	0.11		0.11	0.43	-0.57		-0.57	-2.21
Erosion / Bank Caving		0.28	1.12	4.34					0.00	-0.28	-1.12	-4.34
Boat Survey Erosion					0.28	1.12	4.34	4.34	0.00	0.28	1.12	4.34
<i>LMA Totals:</i>	0.89	0.28	2.01	7.78*	0.13	0.28	1.25	4.84*	-0.76	0.00	-0.76	-2.94

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

ST0002		Total LMA Miles		22.37									
East Levee Sutter Bypass		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control						0.07		0.07	0.31	0.07		0.07	0.31
Erosion / Bank Caving			0.02	0.08	0.36					0.00	-0.02	-0.08	-0.36
LMA Totals:		0.00	0.02	0.08	0.36*	0.07	0.00	0.07	0.31	0.07	-0.02	-0.01	-0.04

ST0003		Total LMA Miles		27.30									
East Levee Sacramento River		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		0.04		0.04	0.15	0.55		0.55	2.02	0.51		0.51	1.87
Trim / Thin Trees		1.38		1.38	5.06	0.44		0.44	1.61	-0.94		-0.94	-3.44
Encroachments		0.14		0.14	0.51	0.26		0.26	0.95	0.12		0.12	0.44
Animal Control		0.14		0.14	0.51	1.30		1.30	4.76	1.16		1.16	4.25
Slope Stability						0.02		0.02	0.07	0.02		0.02	0.07
Erosion / Bank Caving		0.04		0.04	0.15					-0.04		-0.04	-0.15
LMA Totals:		1.74	0.00	1.74	6.37	2.57	0.00	2.57	9.41	0.83	0.00	0.83	3.04

ST0004		Total LMA Miles		2.00									
East Levee Yolo Bypass		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		0.58		0.58	29.00					-0.58		-0.58	-29.00
Trim / Thin Trees		0.18		0.18	9.00					-0.18		-0.18	-9.00
LMA Totals:		0.76	0.00	0.76	38.00	0.00	0.00	0.00	0.00	-0.76	0.00	-0.76	-38.00

ST0005		Total LMA Miles		1.20									
Hamilton Bend		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		6.21		6.21	517.50					-6.21		-6.21	-517.50
Trim / Thin Trees		6.76		6.76	563.33					-6.76		-6.76	-563.33
Crown Surface / Depressions / Rutting		3.38		3.38	281.67	1.05		1.05	87.50	-2.33		-2.33	-194.17
LMA Totals:		16.35	0.00	16.35	1,362.50	1.05	0.00	1.05	87.50	-15.30	0.00	-15.30	1,275.00

ST0006		Total LMA Miles		0.50									
Nelson Bend		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation		0.08	1.00	4.08	816.00	1.10		1.10	220.00	1.02	-1.00	-2.98	-596.00
Trim / Thin Trees		0.66		0.66	132.00	0.44		0.44	88.00	-0.22		-0.22	-44.00
LMA Totals:		0.74	1.00	4.74	948.00	1.54	0.00	1.54	308.00	0.80	-1.00	-3.20	-640.00

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

ST0007 Putah Creek		Total LMA Miles		16.29		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Overall LMA Rating		M				Overall LMA Rating				A							
Vegetation		0.17		0.17	1.04					-0.17		-0.17	-1.04				
Trim / Thin Trees		0.68		0.68	4.17	0.23		0.23	1.41	-0.45		-0.45	-2.76				
Encroachments		0.79		0.79	4.85	0.05		0.05	0.31	-0.74		-0.74	-4.54				
Animal Control						0.12		0.12	0.74	0.12		0.12	0.74				
LMA Totals:		1.64	0.00	1.64	10.07	0.40	0.00	0.40	2.46	-1.24	0.00	-1.24	-7.61				

ST0008 Sacramento Bypass		Total LMA Miles		3.56		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Overall LMA Rating		A				Overall LMA Rating				A							
Encroachments		0.03		0.03	0.84	0.01		0.01	0.28	-0.02		-0.02	-0.56				
LMA Totals:		0.03	0.00	0.03	0.84	0.01	0.00	0.01	0.28	-0.02	0.00	-0.02	-0.56				

ST0009 Tisdale Bypass		Total LMA Miles		9.00		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Overall LMA Rating		A				Overall LMA Rating				A							
Vegetation		0.01		0.01	0.11					-0.01		-0.01	-0.11				
Encroachments						0.01		0.01	0.11	0.01		0.01	0.11				
LMA Totals:		0.01	0.00	0.01	0.11	0.01	0.00	0.01	0.11	0.00	0.00	0.00	0.00				

ST0010 Wadsworth Canal		Total LMA Miles		9.32		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Overall LMA Rating		A				Overall LMA Rating				A							
Encroachments						0.01		0.01	0.11	0.01		0.01	0.11				
Animal Control						0.15		0.15	1.61	0.15		0.15	1.61				
Erosion / Bank Caving		0.06		0.06	0.64					-0.06		-0.06	-0.64				
LMA Totals:		0.06	0.00	0.06	0.64	0.16	0.00	0.16	1.72	0.10	0.00	0.10	1.07				

ST0011 West Levee Yolo Bypass		Total LMA Miles		9.35		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Overall LMA Rating		U				Overall LMA Rating				M *							
Trim / Thin Trees		1.62		1.62	17.33					-1.62		-1.62	-17.33				
Encroachments		0.01		0.01	0.11					-0.01		-0.01	-0.11				
Animal Control						0.01		0.01	0.11	0.01		0.01	0.11				
Erosion / Bank Caving		0.15	0.05	0.35	3.74					-0.15	-0.05	-0.35	-3.74				
Boat Survey Erosion						0.15	0.03	0.27	2.89	0.15	0.03	0.27	2.89				
LMA Totals:		1.78	0.05	1.98	21.18	0.16	0.03	0.28	2.99*	-1.62	-0.02	-1.70	-18.18				

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Sacramento River Basin (cont.)

ST0012	Total LMA Miles		12.46										
Willow Slough Bypass	Fall 2007				Fall 2008				Change				
	Overall LMA Rating				Overall LMA Rating								
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Animal Control					0.21		0.21	1.69	0.21		0.21	1.69	
Erosion / Bank Caving	0.54		0.54	4.33					-0.54		-0.54	-4.33	
Boat Survey Erosion					0.54		0.54	4.33	0.54		0.54	4.33	
<i>LMA Totals:</i>	0.54	0.00	0.54	4.33	0.75	0.00	0.75	6.02	0.21	0.00	0.21	1.69	

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin

NA0010		Total LMA Miles		191.40													
Lower San Joaquin Levee District		Fall 2007				Fall 2008				Change							
		Overall LMA Rating		M		Overall LMA Rating		M *									
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %					
Vegetation	21.94		21.94	11.46	9.86		9.86	5.15	-12.08		-12.08	-6.31					
Trim / Thin Trees	0.18		0.18	0.09	0.03		0.03	0.02	-0.15		-0.15	-0.08					
Encroachments	1.72		1.72	0.90		0.01	0.04	0.02	-1.72	0.01	-1.68	-0.88					
Animal Control	0.85		0.85	0.44	0.70		0.70	0.37	-0.15		-0.15	-0.08					
Slope Stability	1.61		1.61	0.84					-1.61		-1.61	-0.84					
Erosion / Bank Caving	0.08	0.01	0.12	0.06					-0.08	-0.01	-0.12	-0.06					
Crown Surface / Depressions / Rutting	0.54		0.54	0.28					-0.54		-0.54	-0.28					
Rip Rap Revetments	0.13		0.13	0.07					-0.13		-0.13	-0.07					
Vegetation & Obstructions	0.13	0.02	0.21	0.11	0.06		0.06	0.03	-0.07	-0.02	-0.15	-0.08					
Erosion Areas	0.01		0.01	0.01					-0.01		-0.01	-0.01					
Flap Gates	0.01		0.01	0.01					-0.01		-0.01	-0.01					
Concrete Surfaces	0.01		0.01	0.01					-0.01		-0.01	-0.01					
Boat Survey Erosion						0.06	0.24	0.13	0.00	0.06	0.24	0.13					
LMA Totals:	27.21	0.03	27.33	14.28	10.65	0.07	10.93	5.71*	-16.56	0.04	-16.40	-8.57					

NA0011		Total LMA Miles		26.70													
Madera County FCWCA		Fall 2007				Fall 2008				Change							
		Overall LMA Rating		U		Overall LMA Rating		U									
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %					
Vegetation	24.56		24.56	91.99	26.16	2.33	35.48	132.88	1.60	2.33	10.92	40.90					
Trim / Thin Trees	1.02		1.02	3.82	0.18	0.05	0.38	1.42	-0.84	0.05	-0.64	-2.40					
Encroachments	0.72	0.08	1.04	3.90	0.21	0.94	3.97	14.87	-0.51	0.86	2.93	10.97					
Animal Control	8.85	6.07	33.13	124.08	7.69	1.34	13.05	48.88	-1.16	-4.73	-20.08	-75.21					
Erosion / Bank Caving	0.10		0.10	0.38	0.02	0.04	0.18	0.67	-0.08	0.04	0.08	0.30					
Crown Surface / Depressions / Rutting	21.41	0.01	21.45	80.34		0.01	0.04	0.15	-21.41		-21.41	-80.19					
Boat Survey Erosion					0.10		0.10	0.38	0.10		0.10	0.38					
LMA Totals:	56.66	6.16	81.30	304.49	34.36	4.71	53.20	199.25	-22.30	-1.45	-28.10	-105.24					

NA0013		Total LMA Miles		6.30													
Merced County Stream Group		Fall 2007				Fall 2008				Change							
		Overall LMA Rating		U		Overall LMA Rating		U									
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %					
Vegetation	0.34		0.34	5.40					-0.34		-0.34	-5.40					
Animal Control	0.85		0.85	13.49	1.10	2.33	10.42	165.40	0.25	2.33	9.57	151.90					
Slope Stability	0.64		0.64	10.16					-0.64		-0.64	-10.16					
Erosion / Bank Caving	0.04	0.14	0.60	9.52					-0.04	-0.14	-0.60	-9.52					
Crown Surface / Depressions / Rutting					0.10		0.10	1.59	0.10		0.10	1.59					
Boat Survey Erosion					0.02	0.01	0.06	0.95	0.02	0.01	0.06	0.95					
LMA Totals:	1.87	0.14	2.43	38.57	1.22	2.34	10.58	167.94	-0.65	2.20	8.15	129.37					

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin (cont.)

NA0017		Total LMA Miles		104.50									
San Joaquin County Flood Control District		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
		U				M *							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	2.61	0.01	2.65	2.54	2.52		2.52	2.41	-0.09	-0.01	-0.13	-0.12	
Trim / Thin Trees	6.60		6.60	6.32	0.60		0.60	0.57	-6.00		-6.00	-5.74	
Encroachments	3.33	0.31	4.57	4.37	1.59	0.25	2.59	2.48	-1.74	-0.06	-1.98	-1.89	
Animal Control					0.29		0.29	0.28	0.29		0.29	0.28	
Slope Stability					0.03		0.03	0.03	0.03		0.03	0.03	
Erosion / Bank Caving	0.07	1.07	4.35	4.16	0.05		0.05	0.05	-0.02	-1.07	-4.30	-4.11	
Crown Surface / Depressions / Rutting	10.58	0.07	10.86	10.39	0.81		0.81	0.78	-9.77	-0.07	-10.05	-9.62	
Repair Gates		0.03	0.12	0.11					0.00	-0.03	-0.12	-0.11	
Erosion Areas	0.01		0.01	0.01					-0.01		-0.01	-0.01	
Flap Gates						0.01	0.04	0.04	0.00	0.01	0.04	0.04	
Boat Survey Erosion					0.06	0.81	3.30	3.16	0.06	0.81	3.30	3.16	
LMA Totals:	23.20	1.49	29.16	27.90	5.95	1.07	10.23	9.79*	-17.25	-0.42	-18.93	-18.11	

RD0001		Total LMA Miles		1.20									
Reclamation District No. 0001		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
		M				A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	0.14		0.14	11.67					-0.14		-0.14	-11.67	
Trim / Thin Trees	0.03		0.03	2.50					-0.03		-0.03	-2.50	
Erosion / Bank Caving	0.01		0.01	0.83					-0.01		-0.01	-0.83	
Boat Survey Erosion					0.01		0.01	0.83	0.01		0.01	0.83	
LMA Totals:	0.18	0.00	0.18	15.00	0.01	0.00	0.01	0.83	-0.17	0.00	-0.17	-14.17	

RD0017		Total LMA Miles		16.20									
Reclamation District No. 0017		Fall 2007				Fall 2008				Change			
		Overall LMA Rating				Overall LMA Rating							
		U				U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	16.18	16.34	81.54	503.33	0.45	0.02	0.53	3.27	-15.73	-16.32	-81.01	-500.06	
Trim / Thin Trees	0.36		0.36	2.22	0.54	0.25	1.54	9.51	0.18	0.25	1.18	7.28	
Encroachments	0.08		0.08	0.49	0.10		0.10	0.62	0.02		0.02	0.12	
Animal Control	14.37		14.37	88.70	1.86	0.04	2.02	12.47	-12.51	0.04	-12.35	-76.23	
Slope Stability					0.01		0.01	0.06	0.01		0.01	0.06	
Erosion / Bank Caving		0.04	0.16	0.99					0.00	-0.04	-0.16	-0.99	
Repair Gates					0.02		0.02	0.12	0.02		0.02	0.12	
LMA Totals:	30.99	16.38	96.51	595.74	2.98	0.31	4.22	26.05	-28.01	-16.07	-92.29	-569.69	

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin (cont.)

Rated Item	Total LMA Miles		Fall 2007		Fall 2008				Change			
	4.10		U		U							
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.02		0.02	0.49	0.33		0.33	8.05	0.31		0.31	7.56
Trim / Thin Trees	0.07	0.03	0.19	4.63					-0.07	-0.03	-0.19	-4.63
Encroachments	0.03		0.03	0.73	0.03		0.03	0.73	0.00			0.00
Animal Control	1.89		1.89	46.10	0.40		0.40	9.76	-1.49		-1.49	-36.34
Slope Stability					0.05		0.05	1.22	0.05		0.05	1.22
Erosion / Bank Caving	0.04	0.36	1.48	36.10	0.03		0.03	0.73	-0.01	-0.36	-1.45	-35.37
Crown Surface / Depressions / Rutting					0.38		0.38	9.27	0.38		0.38	9.27
Flap Gates	0.01		0.01	0.24	0.01		0.01	0.24	0.00			0.00
Boat Survey Erosion					0.09	0.29	1.25	30.49	0.09	0.29	1.25	30.49
LMA Totals:	2.06	0.39	3.62	88.29	1.32	0.29	2.48	60.49	-0.74	-0.10	-1.14	-27.80

Rated Item	Total LMA Miles		Fall 2007		Fall 2008				Change			
	6.30		U		U							
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.65	0.19	1.41	22.38	0.07	0.08	0.39	6.19	-0.58	-0.11	-1.02	-16.19
Trim / Thin Trees	1.13		1.13	17.94	0.58		0.58	9.21	-0.55		-0.55	-8.73
Encroachments	0.09	0.14	0.65	10.32	0.44	0.01	0.48	7.62	0.35	-0.13	-0.17	-2.70
Animal Control	1.04		1.04	16.51	0.63		0.63	10.00	-0.41		-0.41	-6.51
Slope Stability	0.26		0.26	4.13	0.16		0.16	2.54	-0.10		-0.10	-1.59
Erosion / Bank Caving	0.22	0.01	0.26	4.13	0.25	0.01	0.29	4.60	0.03		0.03	0.48
Crown Surface / Depressions / Rutting					0.02	0.05	0.22	3.49	0.02	0.05	0.22	3.49
Metal Pipes	0.01		0.01	0.16					-0.01		-0.01	-0.16
Boat Survey Erosion					0.02		0.02	0.32	0.02		0.02	0.32
LMA Totals:	3.40	0.34	4.76	75.56	2.17	0.15	2.77	43.97	-1.23	-0.19	-1.99	-31.59

Rated Item	Total LMA Miles		Fall 2007		Fall 2008				Change			
	10.30		U		U							
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.02	0.01	3.06	29.71	7.10	0.45	8.90	86.41	4.08	0.44	5.84	56.70
Trim / Thin Trees	0.69		0.69	6.70	0.83		0.83	8.06	0.14		0.14	1.36
Encroachments	0.56	0.24	1.52	14.76	0.52		0.52	5.05	-0.04	-0.24	-1.00	-9.71
Animal Control	1.36		1.36	13.20	0.36		0.36	3.50	-1.00		-1.00	-9.71
Slope Stability	0.02		0.02	0.19	0.05		0.05	0.49	0.03		0.03	0.29
Erosion / Bank Caving	0.12		0.12	1.17	0.01		0.01	0.10	-0.11		-0.11	-1.07
Crown Surface / Depressions / Rutting					0.06		0.06	0.58	0.06		0.06	0.58
Erosion Areas	0.01		0.01	0.10					-0.01		-0.01	-0.10
Boat Survey Erosion						0.04	0.16	1.55	0.00	0.04	0.16	1.55
LMA Totals:	5.78	0.25	6.78	65.83	8.93	0.49	10.89	105.73	3.15	0.24	4.11	39.90

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin (cont.)

RD1602		Total LMA Miles		6.30													
Reclamation District No. 1602		Fall 2007				Fall 2008				Change							
		Overall LMA Rating				Overall LMA Rating											
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %				
Vegetation		0.18		0.18	2.86	3.89		3.89	61.75	3.71		3.71	58.89				
Trim / Thin Trees						0.15		0.15	2.38	0.15		0.15	2.38				
Encroachments		0.22		0.22	3.49	0.04		0.04	0.64	-0.18		-0.18	-2.86				
Animal Control		5.02		5.02	79.68	1.47		1.47	23.33	-3.55		-3.55	-56.35				
Slope Stability						0.01		0.01	0.16	0.01		0.01	0.16				
Erosion / Bank Caving			0.01	0.04	0.63					0.00	-0.01	-0.04	-0.63				
Crown Surface / Depressions / Rutting		1.57		1.57	24.92	0.47		0.47	7.46	-1.10		-1.10	-17.46				
Encroachments						0.01		0.01	0.16	0.01		0.01	0.16				
LMA Totals:		6.99	0.01	7.03	111.59	6.04	0.00	6.04	95.87	-0.95	-0.01	-0.99	-15.71				

RD2031		Total LMA Miles		13.20													
Reclamation District No. 2031		Fall 2007				Fall 2008				Change							
		Overall LMA Rating				Overall LMA Rating											
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %				
Vegetation		3.78		3.78	28.64	0.11		0.11	0.83	-3.67		-3.67	-27.80				
Trim / Thin Trees		2.69		2.69	20.38	0.22		0.22	1.67	-2.47		-2.47	-18.71				
Encroachments		0.27	0.90	3.87	29.32	0.01		0.01	0.08	-0.26	-0.90	-3.86	-29.24				
Slope Stability			0.90	3.60	27.27					0.00	-0.90	-3.60	-27.27				
Erosion / Bank Caving			0.09	0.36	2.73					0.00	-0.09	-0.36	-2.73				
Crown Surface / Depressions / Rutting		2.42		2.42	18.33		0.09	0.36	2.73	-2.42	0.09	-2.06	-15.61				
Boat Survey Erosion							0.10	0.40	3.03	0.00	0.10	0.40	3.03				
LMA Totals:		9.16	1.89	16.72	126.67	0.34	0.19	1.10	8.33*	-8.82	-1.70	-15.62	-118.33				

RD2058		Total LMA Miles		6.70													
Reclamation District No. 2058		Fall 2007				Fall 2008				Change							
		Overall LMA Rating				Overall LMA Rating											
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %				
Vegetation		6.71	0.58	9.03	134.78	0.58	0.05	0.78	11.64	-6.13	-0.53	-8.25	-123.13				
Trim / Thin Trees		0.37		0.37	5.52	0.18	0.21	1.02	15.22	-0.19	0.21	0.65	9.70				
Encroachments		10.91		10.91	162.84	0.03		0.03	0.45	-10.88		-10.88	-162.39				
Animal Control		13.30		13.30	198.51					-13.30		-13.30	-198.51				
Slope Stability						0.01		0.01	0.15	0.01		0.01	0.15				
Erosion / Bank Caving			0.08	0.32	4.78					0.00	-0.08	-0.32	-4.78				
Boat Survey Erosion							0.04	0.16	2.39	0.00	0.04	0.16	2.39				
LMA Totals:		31.29	0.66	33.93	506.42	0.80	0.30	2.00	29.85	-30.49	-0.36	-31.93	-476.57				

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin (cont.)

RD2062 Reclamation District No. 2062		Total LMA Miles		12.30		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
		Overall LMA Rating				U				Overall LMA Rating				M *			
Vegetation		0.01		0.01	0.08	0.05		0.05	0.41	0.04		0.04	0.33			0.04	0.33
Encroachments		5.95		5.95	48.37					-5.95		-5.95	-48.37				
Erosion / Bank Caving		0.05	0.08	0.37	3.01					-0.05	-0.08	-0.37	-3.01				
Boat Survey Erosion						0.03	0.12	0.51	4.15	0.03	0.12	0.51	4.15				
LMA Totals:		6.01	0.08	6.33	51.46	0.08	0.12	0.56	4.55*	-5.93	0.04	-5.77	-46.91				

RD2063 Reclamation District No. 2063		Total LMA Miles		10.60		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
		Overall LMA Rating				U				Overall LMA Rating				U			
Vegetation		24.47	0.61	26.91	253.87	6.59		6.59	62.17	-17.88	-0.61	-20.32	-191.70				
Trim / Thin Trees		0.99		0.99	9.34	0.03		0.03	0.28	-0.96		-0.96	-9.06				
Encroachments		0.52		0.52	4.91	0.02	0.01	0.06	0.57	-0.50	0.01	-0.46	-4.34				
Animal Control		0.17		0.17	1.60					-0.17		-0.17	-1.60				
Slope Stability						0.01		0.01	0.09	0.01		0.01	0.09				
Erosion / Bank Caving		0.96		0.96	9.06					-0.96		-0.96	-9.06				
Crown Surface / Depressions / Rutting		0.58		0.58	5.47	0.34		0.34	3.21	-0.24		-0.24	-2.26				
Flap Gates						0.02		0.02	0.19	0.02		0.02	0.19				
Sluice / Slide Gates							0.01	0.04	0.38	0.00	0.01	0.04	0.38				
Boat Survey Erosion						0.01		0.01	0.09	0.01		0.01	0.09				
LMA Totals:		27.69	0.61	30.13	284.25	7.02	0.02	7.10	66.98	-20.67	-0.59	-23.03	-217.26				

RD2064 Reclamation District No. 2064		Total LMA Miles		11.90		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
		Overall LMA Rating				U				Overall LMA Rating				M			
Vegetation		14.45		14.45	121.43					-14.45		-14.45	-121.43				
Trim / Thin Trees		2.89		2.89	24.29					-2.89		-2.89	-24.29				
Encroachments		0.09		0.09	0.76					-0.09		-0.09	-0.76				
Animal Control		5.82		5.82	48.91	1.30		1.30	10.92	-4.52		-4.52	-37.98				
Erosion / Bank Caving						0.01		0.01	0.08	0.01		0.01	0.08				
Crown Surface / Depressions / Rutting		3.00		3.00	25.21					-3.00		-3.00	-25.21				
LMA Totals:		26.25	0.00	26.25	220.59	1.31	0.00	1.31	11.01	-24.94	0.00	-24.94	-209.58				

RD2075 Reclamation District No. 2075		Total LMA Miles		7.50		Fall 2007				Fall 2008				Change			
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
		Overall LMA Rating				U				Overall LMA Rating				U			
Vegetation		3.77		3.77	50.27	3.71		3.71	49.47	-0.06		-0.06	-0.80				
Trim / Thin Trees		0.23		0.23	3.07	0.05		0.05	0.67	-0.18		-0.18	-2.40				
Encroachments		0.09	0.19	0.85	11.33	0.38	0.01	0.42	5.60	0.29	-0.18	-0.43	-5.73				
Erosion / Bank Caving			0.02	0.08	1.07					0.00	-0.02	-0.08	-1.07				
Boat Survey Erosion							0.03	0.12	1.60	0.00	0.03	0.12	1.60				
LMA Totals:		4.09	0.21	4.93	65.73	4.14	0.04	4.30	57.33	0.05	-0.17	-0.63	-8.40				

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin (cont.)

RD2085 Reclamation District No. 2085	Total LMA Miles		6.20									
	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	10.41		10.41	167.90	0.79		0.79	12.74	-9.62		-9.62	-155.16
Trim / Thin Trees	0.01		0.01	0.16	1.47		1.47	23.71	1.46		1.46	23.55
Encroachments	2.71		2.71	43.71	0.02		0.02	0.32	-2.69		-2.69	-43.39
Erosion / Bank Caving	0.01		0.01	0.16	0.01		0.01	0.16	0.00			0.00
Crown Surface / Depressions / Rutting	0.85		0.85	13.71	0.05		0.05	0.81	-0.80		-0.80	-12.90
Underseepage Relief Wells						0.02	0.08	1.29	0.00	0.02	0.08	1.29
Repair Gates	0.01		0.01	0.16					-0.01		-0.01	-0.16
LMA Totals:	14.00	0.00	14.00	225.81	2.34	0.02	2.42	39.03	-11.66	0.02	-11.58	-186.77

RD2089 Reclamation District No. 2089	Total LMA Miles		2.90									
	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.21		1.21	41.72	0.26	2.08	8.58	295.86	-0.95	2.08	7.37	254.14
Trim / Thin Trees	0.81		0.81	27.93	0.85	0.12	1.33	45.86	0.04	0.12	0.52	17.93
Encroachments	0.02		0.02	0.69					-0.02		-0.02	-0.69
Animal Control					0.03	0.01	0.07	2.41	0.03	0.01	0.07	2.41
Erosion / Bank Caving	0.03	0.03	0.15	5.17					-0.03	-0.03	-0.15	-5.17
Crown Surface / Depressions / Rutting					0.76		0.76	26.21	0.76		0.76	26.21
Boat Survey Erosion					0.04	0.03	0.16	5.52	0.04	0.03	0.16	5.52
LMA Totals:	2.07	0.03	2.19	75.52	1.94	2.24	10.90	375.86	-0.13	2.21	8.71	300.34

RD2091 Reclamation District No. 2091	Total LMA Miles		7.92									
	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.62		0.62	7.83	0.62		0.62	7.83
Trim / Thin Trees					0.16		0.16	2.02	0.16		0.16	2.02
Encroachments	0.01		0.01	0.13					-0.01		-0.01	-0.13
LMA Totals:	0.01	0.00	0.01	0.13	0.78	0.00	0.78	9.85	0.77	0.00	0.77	9.72

RD2092 Reclamation District No. 2092	Total LMA Miles		3.80									
	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.07		0.07	1.84	0.07		0.07	1.84
Encroachments					0.01		0.01	0.26	0.01		0.01	0.26
Slope Stability					0.01		0.01	0.26	0.01		0.01	0.26
Erosion / Bank Caving	0.14		0.14	3.68					-0.14		-0.14	-3.68
Boat Survey Erosion					0.14		0.14	3.68	0.14		0.14	3.68
LMA Totals:	0.14	0.00	0.14	3.68	0.23	0.00	0.23	6.05	0.09	0.00	0.09	2.37

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin (cont.)

RD2094	Total LMA Miles		3.30									
Reclamation District No. 2094	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments	5.41		5.41	163.94					-5.41		-5.41	-163.94
Animal Control					0.19		0.19	5.76	0.19		0.19	5.76
Erosion / Bank Caving					0.01		0.01	0.30	0.01		0.01	0.30
<i>LMA Totals:</i>	5.41	0.00	5.41	163.94	0.20	0.00	0.20	6.06	-5.21	0.00	-5.21	-157.88

RD2095	Total LMA Miles		4.90									
Reclamation District No. 2095	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.61		3.61	73.67	1.82		1.82	37.14	-1.79		-1.79	-36.53
Trim / Thin Trees					0.72		0.72	14.69	0.72		0.72	14.69
Encroachments	1.45		1.45	29.59	0.02		0.02	0.41	-1.43		-1.43	-29.18
Erosion / Bank Caving	0.03	0.03	0.15	3.06	0.81		0.81	16.53	0.78	-0.03	0.66	13.47
Boat Survey Erosion					0.01	0.06	0.25	5.10	0.01	0.06	0.25	5.10
<i>LMA Totals:</i>	5.09	0.03	5.21	106.33	3.38	0.06	3.62	73.88	-1.71	0.03	-1.59	-32.45

RD2096	Total LMA Miles		0.20									
Reclamation District No. 2096	Fall 2007				Fall 2008				Change			
	Overall LMA Rating A				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.01		0.01	5.00	0.01		0.01	5.00
Animal Control					0.01		0.01	5.00	0.01		0.01	5.00
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.02	0.00	0.02	10.00	0.02	0.00	0.02	10.00

RD2101	Total LMA Miles		3.50									
Reclamation District No. 2101	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.38		2.38	68.00	2.75		2.75	78.57	0.37		0.37	10.57
Trim / Thin Trees	0.85		0.85	24.29	1.88		1.88	53.71	1.03		1.03	29.43
Animal Control	0.24		0.24	6.86	0.14		0.14	4.00	-0.10		-0.10	-2.86
Erosion / Bank Caving		0.09	0.36	10.29		0.02	0.08	2.29	0.00	-0.07	-0.28	-8.00
Crown Surface / Depressions / Rutting	1.62		1.62	46.29	0.20		0.20	5.71	-1.42		-1.42	-40.57
Boat Survey Erosion					0.10	0.40	1.43	11.43	0.00	0.10	0.40	11.43
<i>LMA Totals:</i>	5.09	0.09	5.45	155.71	4.97	0.12	5.45	155.71	-0.12	0.03	0.00	0.00

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

San Joaquin River Basin (cont.)

RD2107	Total LMA Miles		4.20									
Reclamation District No. 2107	Fall 2007				Fall 2008				Change			
	Overall LMA Rating				Overall LMA Rating							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.22		0.22	5.24	0.22		0.22	5.24
Trim / Thin Trees	0.01		0.01	0.24	0.05		0.05	1.19	0.04		0.04	0.95
Encroachments	0.83		0.83	19.76	0.01		0.01	0.24	-0.82		-0.82	-19.52
<i>LMA Totals:</i>	0.84	0.00	0.84	20.00	0.28	0.00	0.28	6.67	-0.56	0.00	-0.56	-13.33

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2007

Miscellaneous Streams & Basins

MA0017	Total LMA Miles		3.90									
Maintenance Area 0017	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	4.08		4.08	104.62		3.13	12.52	321.03	-4.08	3.13	8.44	216.41
Trim / Thin Trees	2.89		2.89	74.10		3.12	12.48	320.00	-2.89	3.12	9.59	245.90
<i>LMA Totals:</i>	6.97	0.00	6.97	178.72	0.00	6.25	25.00	641.03	-6.97	6.25	18.03	462.31

NA0009	Total LMA Miles		11.10									
Lake County Watershed Protection District	Fall 2007				Fall 2008				Change			
	Overall LMA Rating M				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.46		0.46	4.14	0.23		0.23	2.07	-0.23		-0.23	-2.07
Trim / Thin Trees	0.54		0.54	4.87	0.19		0.19	1.71	-0.35		-0.35	-3.15
Encroachments	0.06		0.06	0.54	0.04		0.04	0.36	-0.02		-0.02	-0.18
Erosion / Bank Caving	0.05		0.05	0.45	0.10		0.10	0.90	0.05		0.05	0.45
<i>LMA Totals:</i>	1.11	0.00	1.11	10.00	0.56	0.00	0.56	5.05	-0.55	0.00	-0.55	-4.96

NA0015	Total LMA Miles		3.20									
Plumas County	Fall 2007				Fall 2008				Change			
	Overall LMA Rating U				Overall LMA Rating A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	6.44		6.44	201.25					-6.44		-6.44	-201.25
Erosion / Bank Caving	0.02		0.02	0.63					-0.02		-0.02	-0.63
<i>LMA Totals:</i>	6.46	0.00	6.46	201.88	0.00	0.00	0.00	0.00	-6.46	0.00	-6.46	-201.88

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.